REDACTED

MATERIAL EVALUATION REPORT

Client: A A AUSSI PALLETS

Subject: EVALUATION OF WOODEN PALLETS TO AS 4068

Client Reference: REDACTED

Order Number: 1857

Correlation/Report No.: 4941-0340/1

1.0 INTRODUCTION.

It was requested three wooden pallets be tested in accordance with AS 4068 "Flat Pallets for Material Handling" - 1993. The pallets were nominally 2 way units comprised of three bearers with 7 boards on the top (1 entry at each end and 6 intermediate) deck and 5 on the lower deck (1 entry at each ends and 3 intermediate centrally located) as per figure A2 of AS 4068 - 1993. All pallets were to be tested in the "green" condition using timbers in the as supplied condition.

2.0 PALLET CONDITIONING

Each of the supplied pallets was conditioned for a minimum of 48 hours using condition set B as per table 1 of section 5 in AS 4068 – 1993 (22+/-2°C and 65+/-5% RH) with all testing done at ambient conditions. All samples were returned to the condition chamber for a minimum of 1 hour between tests.

CONTACT US FOR MORE INFORMATION

Chris Vines
Senior Metallurgical Engineer
Victoria, AUSTRALIA